

Report run on 07/22/2010

CERT_WAVE_NAME	SPECS_CERTIFIED	PRODUCT_TYPE_NAME	MANUFACTURER	CABLELABS_NAME	MODEL_NUM	SOFTWARE_REVISION	HARDWARE_REVISION	OEM_VENDOR_ID	CB_DECISION_PUBLIC_COMMENT
CW76	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Cisco	CVTG761	DPQ3925	DPQ3925-P15-14-v302r121003a	1.0		
CW75	D3.0,D2.0,D1.1	CM	Motorola	MOTO751	SB6121	2.0.2.33	5.0		
CW75	DSG,D2.0,D1.1	DSG+ECM	Pace Micro Technology	PACE751	RNG200N	2.2.2mp2	V1.0		Verified for Interoperability
CW75	DSG,D2.0,D1.1	DSG+ECM	Pace Micro Technology	PACE752	RNG150N	2.2.2mp2	V1.0		Verified for Interoperability
CW74	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Cisco	CVTG741	DPQ3925	DPQ3925-P15-14-v302r121003a	1.0		
CW74	D3.0,D2.0,D1.1	CM	Cisco	CVTG742	DPC3825	dpc3825-v302r121003a	1.0		
CW74	P1.5,P1.0,D2.0,D1.1	eCMM	Innomedia	INNO741	6528-LC	1.1.13 Fri Mar 5 19:33:30 2010	10.12.0.1		
CW74	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	SMC	SMCN741	SMCD3GNV	2.0.0.26	1A		
CW74	D3.0,D2.0,D1.1	CM	SMC	SMCN742	SMCD3GNB	5.1.6beta3	V1.0		
CW73	D3.0,D2.0,D1.1	CM	Cisco	CVTG731	DPQ3825	dpq3825-v302r171002	1.0		
CW73	DSG,D2.0,D1.1	DSG+ECM	Panasonic	PANA731	PCH2200	2.2.2	V0.90		Verified for Interoperability
CW73	D2.0,D1.1	CM	Ubee Interactive	UBEE731	DDW2610	5.115.1000	4.33.1		
CW73	D3.0,D2.0,D1.1	CM	Zoom	ZOOM731	5341	1.2.1.34	1A	HITR661	
CW72	P1.5,P1.0,D2.0,D1.1	eCMM	Innomedia	INNO721	6528-LC	1.1.12 Thu Nov 5 16:18:15 2009	10.12.0.1		
CW72	P1.5,P1.0,D2.0,D1.1	eCMM-Based	Innomedia	INNO722	eMTA 6528	1.1.12 Thu Nov 5 16:18:15 2009	10.12.0.1		Verified for Interoperability
CW72	P1.5,P1.0,D2.0,D1.1	EMTA	Netgear	NTGR721	CG2000	4.5.11	1.04		
CW72	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Netgear	NTGR722	CVD31XB	4.5.11	1.05		
CW72	D3.0,D2.0,D1.1	CM	SMC	SMCN721	SMCD3GN2	1.5.0.12	1A		
CW72	D3.0,D2.0,D1.1	CM	Thomson	THOM721	DWG875	STB1.00.01	1.0		
CW71	D2.0,D1.1	CM	AM Communications	AMCO711	DSM3	4.5.9.0_01.00-NA	2.0		
CW71	P1.5,P1.0,D2.0,D1.1	EMTA	Arris	ARRI711	TM632A	6.10.4	1		
CW71	D3.0,D2.0,D1.1	CM	Castlenet	CAST711	CBC-381	2.381.51x.001	A2		
CW71	D3.0,D2.0,D1.1	CM	Motorola	MOTO712	SBG6580	SBG6580-3.1.0.0-CW-02-SH	Rev. 1		
CW71	D3.0,D2.0,D1.1	CM	Netgear	NTGR711	CG3200D	V1.3.1.0	1.11		
CW71	D3.0,D2.0,D1.1	CM	Netgear	NTGR712	CMD31B	5.1.4	1.00		
CW71	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	SMC	SMCN711	SMCD3USG	1.5.0.12	1.0		
CW71	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Ubee Interactive	UBEE711	DVW3200	9.2.2000	3.7.1		
CW70	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Cisco	CVTG701	DPQ3212	DPQ3212-P15-15-v302r12906	1.0		
CW70	D3.0,D2.0,D1.1	CM	Dlink	DLIN701	DCM-301	5.1.4	A1		
CW70	D3.0,D2.0,D1.1	eCMM	Juniper Networks	JNPR701	ECM3100-JU	1.4.0.11	1.1		
CW70	D3.0,D2.0,D1.1	CM	Motorola	MOTO701	SB6180	SB6180-3.5.0.0-CW-70-NOSH	Rev1		
CW70	P1.5,P1.0,D2.0,D1.1	EMTA	Motorola	MOTO702	SVG2501	SVG2501-2.0.0.0-CW-04-LTSH	Rev. 1		
CW70	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Netgear	NTGR701	CG3000	4.5.9beta6	1.03		
CW70	D3.0,D2.0,D1.1	CM	Thomson	THOM701	DCW775	STB5.01.01	1.0		
CW70	D3.0,D2.0,D1.1	CM	Ubee Interactive	UBEE701	DDW3610	5.113.2000	4.31		
CW68	P1.5,P1.0,D2.0,D1.1	EMTA	Motorola	MOTO682	SBV5122	SBV5122-2.22.2.2-CWT04-SHPC	2		
CW68	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Motorola	MOTO683	SBV6120	1.1.2.47	Rev 1		
CW68	D2.0,D1.1	CM	Motorola	MOTO684	SBG941	SBG941-2.1.0.0-CW-01-NOSH	1		
CW67	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Arris	ARRI671	TM702G	7.1.12	7.7		
CW67	D3.0,D2.0,D1.1	CM	Arris	ARRI672	WBM750A	3.2.15C	5		
CW67	P1.5,P1.0,D2.0,D1.1	EMTA	Motorola	MOTO671	SVG1501U	2.0.0.0	Rev. 1		
CW67	D3.0,D2.0,D1.1	CM	Motorola	MOTO672	SB6120	1.2.2.45	3.0		
CW67	DSG,D2.0,D1.1	DSG+ECM	Pace Micro Technology	PACE671	RNG110	4.4.3alpha5	V1.0		Verified for Interoperability
CW67	D3.0,D2.0,D1.1	CM	SMC	SMCN671	SMCD3G	1.2.2.45	1.01		
CW67	P1.5,P1.0,D2.0,D1.1	EMTA	Ubee Interactive	UBEE671	DVW2200	6.22.1000	3.6.1		
CW67	D3.0,D2.0,D1.1	CM	Ubee Interactive	UBEE672	DDW3600	8.2.1000	4.29		
CW66	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Ambit	AMBI661	DVM3210	11.0.0.1	2.41		
CW66	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Cisco	CVTG661	DPQ3202	dpq3202-P15-15-v303r22903	2.0		

CERT_WAVE_NAME	SPECS_CERTIFIED	PRODUCT_TYPE_NAME	MANUFACTURER	CABLELABS_NAME	MODEL_NUM	SOFTWARE_REVISION	HARDWARE_REVISION	OEM_VENDOR_ID	CB_DECISION_PUBLIC_COMMENT
CW66	D3.0,D2.0,D1.1	CM	Hitron	HITR661	BRG-35503	1.2.1.34	1A		
CW66	D2.0,D1.1	CM	Motorola	MOTO661	SB5101N	SB5101NU-2.1.0.0-CW-04-NOSH	1.0		
CW66	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Motorola	MOTO662	SBV6220	1.1.1.29	2		
CW65	D3.0,D2.0,D1.1	CM	Ambit	AMBI651	DDM35000	3.19.1001	1.42		
CW65	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Ambit	AMBI652	DVM32000	3.21.1001	2.55		
CW65	D3.0,D2.0,D1.1	CM	Ambit	AMBI653	U10C035	1.0.0.2	1.0		
CW65	D2.0,D1.1	CM	Cisco	CVTG651	DPC2100R3	dpc2100r3-v202r12901	3.0		
CW65	D3.0,D2.0,D1.1	CM	Cisco	CVTG652	DPC3000	dpc3000-v303r22901	2.0		
CW65	D3.0,D2.0,D1.1	CM	Cisco	CVTG653	DPC3010	v302r22901	1.0		
CW65	P1.5,P1.0,D2.0,D1.1	EMTA	Dlink	DLIN651	DCM-604	81.700V.4216.729.001	1.0	CAST641	
CW65	D2.0,D1.1	CM	Motorola	MOTO651	SBG901	SBG901N-2.1.0.0-CW-01-NOSH	1.0		
CW65	D3.0,D2.0,D1.1	CM	Netgear	NTGR651	CMD31T	1.2.0.23	1.02A		
CW65	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Netgear	NTGR652	CVD31XT	1.1.0.18	1.04		
CW65	D3.0,D2.0,D1.1	CM	SMC	SMCN651	SMCD3CM	1.2.0.23	1.02		
CW65	D3.0,D2.0,D1.1	CM	Thomson	THOM651	DCM475	STAC.01.00	1.0		
CW65	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Thomson	THOM652	DHG575	STA7.01.00	1.0		
CW65	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Zyxel	ZYXE651	P-2910	1.1.0.18	94.4		
CW64	P1.5,P1.0,D3.0,D2.0,D1.1	CMTS+PC	Casa Systems	2CASA641	C10200	5.1.1	1.1		
CW64	P1.5,P1.0,D2.0,D1.1	EMTA	Castlenet	CAST641	Netmaster CBW-700V	81.700V.4216.729.001	V1.0		
CW64	DSG,D2.0,D1.1	DSG+ECM	Cisco	CVTG641	8600	1.5.7000.0105	1.2		Verified for Interoperability
CW64	D2.0,D1.1	CM	Cisco	CVTG643	DPC2325	dpc2325-v202r12811	1.0		
CW64	D2.0,D1.1	CM	Cisco	CVTG644	DPQ2160	dpq2160-v202r12811	2.0		
CW64	D3.0,D2.0,D1.1	CM	Cisco	CVTG645	DPC3000	dpc3000-v303r12810	1.1		
CW64	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Netgear	NTGR641	CVD31XT	1.0.2.22	1.04		
CW64	P1.5,P1.0,D2.0,D1.1	EMTA	Scientific Atlanta	CVTG642	DPQ2425	v202r12811	1.0		
CW64	D3.0,D2.0,D1.1	CM	SMC	SMCN641	SMCD3G	1.1.2.21	1.01		
CW64	P1.5,P1.0,D2.0,D1.1	EMTA	Thomson	THOM641	DHG546	STA5.01.00	1.0		
CW63	D3.0,D2.0,D1.1	CM	Ambit	AMBI631	U10C035	1.0.0.1	1.0		
CW63	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Arris	ARRI631	TM702G	7.1.10	4.0		
CW63	D3.0,D2.0,D1.1	CM	Arris	ARRI632	WBM750A	3.1.6	1.0		
CW63	D3.0,D2.0,D1.1	CM	Hitron	HITR631	BRG-35503	1.1.0.19	1.01		
CW63	D3.0,D2.0,D1.1	CM	Motorola	MOTO631	SB6120	1.1.0.19	1.0		
CW63	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Motorola	MOTO632	SBV6220	1.0.0.21	1.0		
CW63	D3.0,D2.0,D1.1	CM	Netgear	NTGR631	CMD31T	1.1.0.19R01	1.02		
CW63	DSG,D2.0,D1.1	DSG+ECM	Scientific Atlanta	SCIE631	1600	2.1.4000.0302	1.6		Verified for Interoperability
CW63	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Scientific Atlanta	SCIE632	DPQ3202	dpq3202-v303r22810	2.0		
CW63	D3.0,D2.0,D1.1	CM	Scientific Atlanta	SCIE633	DPC3000	dpc3000-v303r12810	2.0		
CW63	D3.0,D2.0,D1.1	CM	SMC	SMCN631	SMCD3CM	1.1.0.19	1.01		
CW62	DSG,D2.0,D1.1	DSG+ECM	Panasonic	PANA621	TZ-PCH2180M	2.0.0	1.07		Verified for Interoperability
CW61	D3.0,D2.0,D1.1	CM	Hitron	HITR611	BRG-35503	1.0.2.31	1.1		
CW61	P1.5,P1.0,D2.0,D1.1	EMTA	Scientific Atlanta	SCIE611	DPQ2202	v202r1287	1.0		
CW60	D2.0,D1.1	CM	Netgear	NTGR601	CGD24G	V4.2.18.R01	1.0		
CW60	D3.0,D2.0,D1.1	CM	Netgear	NTGR602	CMD31T	1.0.0.27R01	1.02		
CW60	P1.5,P1.0,D2.0,D1.1	EMTA	Rembrandt Technologies, LLC	REMB601	REM-8200	23.0.0.12	72.2		
CW60	P1.5,P1.0,D2.0,D1.1	EMTA	Scientific Atlanta	SCIE601	DRG2800	v2.0.2r1285	1.0		
CW60	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Scientific Atlanta	SCIE602	DPQ3202	dpq3202-v303r2285	2.0		
CW60	P1.5,P1.0,D2.0,D1.1	EMTA	Zyxel	ZYXE601	P2900	22.2.2.22	72.2		
CW59	D2.0,D1.1	CM	Ambit	AMBI591	U10C037	2.93.9059	1.0		
CW59	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Arris	ARRI591	TM702G	7.1.3	4.0		
CW59	D3.0,D2.0,D1.1	CM	Arris	ARRI592	WBM750A	7.0.17	1.0		
CW59	P1.5,P1.0,D3.0,D2.0,D1.1	EMTA	Motorola	MOTO591	SBV6220	0.5.0.43	1.0		
CW59	D2.0,D1.1	CM	Scientific Atlanta	SCIE591	DPQ2160	dpq2160-v202r1582	1.0		

CERT_WAVE_NAME	SPECS_CERTIFIED	PRODUCT_TYPE_NAME	MANUFACTURER	CABLELABS_NAME	MODEL_NUM	SOFTWARE_REVISION	HARDWARE_REVISION	OEM_VENDOR_ID	CB_DECISION_PUBLIC_COMMENT
CW58	D3.0,D2.0,D1.1	CM	Ambit	AMBI581	U10C035	1.0.0.0	1.0		
CW58	D3.0,D2.0,D1.1	CMTS	Arris	2ARRI581	C4-CMTS-2100-1	CMTS_V07.00.03.32	3.0		Bronze Qualification - Expired
CW58	D3.0,D2.0,D1.1	CM	Arris	ARRI581	TM702G	7.0.12	1.0		
CW58	D3.0,D2.0,D1.1	CMTS	Casa Systems	2CASA581	C2200 CMTS	5.0.16	1.1		Full Qualification
CW58	D3.0,D2.0,D1.1	CMTS	Casa Systems	2CASA582	C3200 CMTS	5.0.16	3.0.0		Full Qualification
CW58	D3.0,D2.0,D1.1	CMTS	Cisco	2CISC581	uBR10012	Ubr10k2-k9p6u2_CW-mz.122-BRONZE_CW58_FINAL.080218	V01		Bronze Qualification - Expired
CW58	D3.0,D2.0,D1.1	CMTS	Motorola	2MOTO581	BSR 64000	5.1.0T06P19.HXX.KRAU	CHS-0009-01		Bronze Qualification - Expired
CW58	D3.0,D2.0,D1.1	CM	Motorola	MOTO581	SB6120	1.0.0.20	1.0		
CW58	D3.0,D2.0,D1.1	CM	Motorola	MOTO582	SBV6220	1.0.0.20	1.0		
CW58	DSG,D2.0,D1.1	DSG+ECM	Scientific Atlanta	SCIE581	1500	2.1.1000.0108	1.1		Verified for Interoperability
CW58	D3.0,D2.0,D1.1	CM	Scientific Atlanta	SCIE582	DPC3000	dpc3000-v301r2382	1.0		
CW58	D3.0,D2.0,D1.1	CM	SMC	SMCN581	SMCD3CM	1.1.3	1.0		
CW57	P1.5,P1.0,D2.0,D1.1	EMTA	Ambit	AMBI571	U10C034	4.97.1004	1.0		
CW57	D2.0,D1.1	CM	Thomson	THOM571	DHG537	STA0.00.00	1.0		
CW57	P1.5,P1.0,D2.0,D1.1	EMTA	Thomson	THOM572	ACG905	1.0.1	0		
CW56	D3.0,D2.0,D1.1	CMTS	Arris	2ARRI561	C4-CMTS-2100-1	CMTS_V07.00.00.79	3.0		Bronze Qualification - Expired
CW56	D3.0,D2.0,D1.1	CMTS	Casa Systems	2CASA561	C2200 CMTS	5.0.5	1.1		Silver Qualification
CW56	D3.0,D2.0,D1.1	CMTS	Cisco	2CISC561	uBR10012	UBR10K2-K9P6U2_CW-M	UBR10-MC5X20H-X rev v03		Bronze Qualification - Expired
CW56	D2.0,D1.1	eCMM	Maspro	MASP561	ACM6049-SC	2.46	1.13B		
CW56	D2.0,D1.1	CM	Scientific Atlanta	SCIE562	DPC2160	dpc2160-v202r10711	1.0		
CW56	P1.5,P1.0,D2.0,D1.1	EMTA	Thomson	THOM561	DHG536	ST75.01.00	1.0		
CW54	D2.0,D1.1	CM	Arris	ARRI541	TM602G	5.2.12A	02		
CW54	DSG,D2.0,D1.1	DSG+ECM	Scientific Atlanta	SCIE541	8501	1.5.1005.0304	1.4		Verified for Interoperability
CW54	D2.0,D1.1	eCMM	Tollgrade	TOLL541	CMD-GM	3.4.0 Build 3 CxC 3.9.17	1.0.0		
CW53	P1.5,P1.0,D2.0,D1.1	EMTA	Hitron	HITR531	BVG-3642	1.22.1.6	1A		
CW53	P1.5,P1.0,D2.0,D1.1	EMTA	Motorola	MOTO531	SVG2500	SVG2500N-2.3.1.7-ALPHA-00-LTSH	1		
CW52	P1.0	CMS	Huawei	0HWEI521	SOFTX3000	V300R601	OSTA		
CW52	D2.0,D1.1	CM	Rembrandt Technologies, LLC	REMB521	REM-8100	22.2.0.13	56.1		
CW52	D2.0,D1.1	CM	Sling Media	SLNG521	V-Modem007	22.2.0.13	54.7		
CW51	D2.0,D1.1	CM	Ambit	AMBI511	U10C023	2.93.9051	1.0		
CW51	P1.5,P1.0,D2.0,D1.1	EMTA	Motorola	MOTO512	SBV5322	SBV5322-2.22.2.0-CWT03-NOSH	1		
CW51	D2.0,D1.1	CM	Thomson	THOM511	DCM465	ST95.01.00	1.0		
CW50	PCMM	Policy Server	C-Cor	5CCOR501	Not Applicable	1.2	Not Applicable		
CW50	P1.5,P1.0,D2.0,D1.1	EMTA	SMC	SMCN501	SMC8414WG	2.2.2.5	1.0		
CW49	P1.5,P1.0,D2.0,D1.1	EMTA	Motorola	MOTO491	SBV5222	SBV5222-2.22.2.0-CWT06-NOSH	1		
CW49	D2.0,D1.1	CM	Scientific Atlanta	SCIE491	DPC2505	dpc2505-v202r1071	1.0		
CW48	D2.0,D1.1	CM	AM Communications	AMCO481	Model 9362A	1.83	4.0		
CW48	D2.0,D1.1	eCMM-Based	Cisco	CISC481	CISCO815	2.103.1013	2.0		
CW48	D2.0,D1.1	eCMM-Based	Cisco	CISC482	Cisco IAD2431	2.103.1013	2.0		
CW48	D2.0,D1.1	CM	Cisco-Linksys, LLC	LINK481	CM100	0.0.6.13010	54.0		
CW47	D2.0,D1.1	CM	Motorola	MOTO471	SB5102	SB5102N-2.1.0.0-GA-07-NOSH	1		
CW46	D2.0,D1.1	CM	Arris	ARRI461	CM550A	6.1.2	08		
CW45	P1.5,P1.0,D2.0,D1.1	EMTA	Ambit	AMBI451	U10C021	4.90.1003	2.31		
CW45	D2.0,D1.1	eCMM	Cisco	CISC451	HWIC-CABLE-D-2	2.103.1013	2.0		
CW45	D2.0,D1.1	eCMM-Based	Cisco	CISC452	CISCO1841	2.103.1013	2.0		This device was certified as an eCMM-based device with the CISC451 qualified eCMM.
CW45	DSG,D2.0,D1.1	DSG+ECM	Motorola	MOTO451	DCT3412/2305	0.1.4.7-SH	P3		Verified for Interoperability
CW45	C1.1,D2.0,D1.1	Embedded PS	Scientific Atlanta	SCIE451	DPR2325R3	dpr2325r3-v202r1264	3.0		
CW45	PCMM	Policy Server	Siemens	5SIEM451	Primergy TX300 S2	pcs-2.0-CertCW45_08	Primergy TX300 S2		
CW45	M-CMTS	DTIS	Symmetrical	15SYMM451	990-93105-01	IMC-0.9.5 IOC-0.5.30	1A		
CW45	D2.0,D1.1	CM	Thomson	THOM451	DCM425	ST52.05.00	4.1		
CW45	P1.5,P1.0,D2.0,D1.1	EMTA	Thomson	THOM452	DHG535	ST70.02.01	1.1		

CERT_WAVE_NAME	SPECS_CERTIFIED	PRODUCT_TYPE_NAME	MANUFACTURER	CABLELABS_NAME	MODEL_NUM	SOFTWARE_REVISION	HARDWARE_REVISION	OEM_VENDOR_ID	CB_DECISION_PUBLIC_COMMENT
CW43	C1.1,P1.5,P1.0,D2.0,D1.1	CM+MTA+PS	Ambit	AMBI431	U10C022	7.10.1006	2.30		
CW43	P1.0,D2.0,D1.1	EMTA	Scientific Atlanta	SCIE431	DPC2203	v2.0.2r1263	1.1		
CW42	DSG,D1.1	CMTS+DSG	Cisco	2CISC421	uBR7246 VXR/MC28U	12.3(17a)BCc	MC28U:Rev 6.5		
CW42	P1.5,P1.0,D2.0,D1.1	EMTA	Cisco-Linksys, LLC	LINK421	CMP300B2	2.4.11.13010	58.0		
CW42	D2.0,D1.1	CMTS	Motorola	2MOTO421	BSR 2000	1.0.0T01P24.TRAU	520025-001-00 Rev 4		
CW42	P1.0,D2.0,D1.1	EMTA	Tollgrade	TOLL421	CMD-P	3.0.6 Build 2 CxC 3.9.7	1.0.0		Verified for Interoperability
CW42	D2.0,D1.1	CM	Tollgrade	TOLL422	CMD-E	3.0.6 Build 2 CxC 3.9.7	1.0.0		
CW41	D2.0,D1.1	CM	Cisco-Linksys, LLC	LINK412		0.0.6.13010	54.0		
CW41	P1.5,P1.0,D2.0,D1.1	EMTA	Netgear	NTGR411	EM612	3.9.4.4R01	1.01		
CW41	DSG,D1.1	DSG+ECM	Pace Micro Technology	PACE411	TDC575D	1.1.1q001	V1.0		Verified for Interoperability
CW41	C1.1,D2.0,D1.1	Embedded PS	Scientific Atlanta	SCIE411	DPR2320	dpr2320r2-v202r1261	2.0		
CW41	C1.1,P1.0,D2.0,D1.1	CM+MTA+PS	Scientific Atlanta	SCIE412	DPC2434	dpc2434-v202r1261	1.0		
CW41	C1.1,D2.0,D1.1	Embedded PS	Thomson	THOM411	DCW725	ST5A.07.00	5.0		
CW41	C1.1,P1.5,P1.0,D2.0,D1.1	CM+MTA+PS	Thomson	THOM412	DWG855	ST80.01.00	2.0		
CW40	D2.0,D1.1	CM	AM Communications	AMCO401	Model 9360	1.0	5		
CW40	P1.0,D2.0,D1.1	EMTA	Asustek	ASUS401	ACM6149	3.9.4R1000	1.10a		
CW40	D2.0,D1.1	eCMM	ATI	ATY1401	CAFE 1.0	0.1.0.0	1.0		
CW40	PCMM,D1.1	CMTS+MM	Bigband Networks	2BIGB401	Cuda 12000	R6.0.0	Rev 4		
CW40	PCMM,D1.1	CMTS+MM	Cisco	2CISC401	uBR7246 VXR/MC28U	12.3(13a)BCc	MC28U:Rev 6.5		
CW40	P1.0,D2.0,D1.1	EMTA	Cisco-Linksys, LLC	LINK401	CMP200B2	2.0.3.9.6	1.0		
CW40	C1.1,P1.0,D2.0,D1.1	CM+MTA+PS	Cisco-Linksys, LLC	LINK402	WCGP200B2	2.0.3.9.6	1.0		
CW40	D2.0,D1.1	CM	Electroline	ELEC401	DHT-PS-NA-02	1.00	01		
CW40	PCMM	Policy Server	Juniper Networks	5JNPR401	SDX-S1-62300	6.2.0	N/A		
CW40	P1.0,D2.0,D1.1	EMTA	Motorola	MOTO401	SBV5221	SBV5221-2.17.8.6-SCM01-NOSH	1		
CW40	C1.1,P1.0,D2.0,D1.1	CM+MTA+PS	Netgear	NTGR401	CVG824G	3.9.4R0001	1.0.1		
CW40	D2.0,D1.1	CM	Scientific Atlanta	SCIE401	DPC2100R2	v2.0.2r1256	2.1		
CW40	P1.0	MG	Siemens	4SIEM401	hiG 1200	11.80.01.33	S50043-B1606-X-5		
CW40	P1.5,P1.0,D2.0,D1.1	EMTA	Terayon	TERA401	TJ955	17.2.0.7	58.0		
CW40	C1.1,P1.0,D2.0,D1.1	CM+MTA+PS	Thomson	THOM401	DWG855	ST78.01.00	1.0		
CW40	P1.0,D2.0,D1.1	EMTA	Thomson	THOM402	DHG525	ST62.09.00	5.1		
CW39	D2.0,D1.1	eCMM	Askey Computer Corp.	ASKE391	CMM300	2.0.3.8.5	1.0		
CW39	C1.1,D2.0,D1.1	Embedded PS	SMC	SMCN391	SMC8014WG-CHM	3.17.11	1.65		
CW39	D2.0,D1.1	CM	WideView Technology	WIDE391	WM-100	17.1.7.17	35.4.2		
CW38	D2.0,D1.1	CM	Alpha	ALPH381	Alpha CM-H	2.01.01AH1.0	1.0		
CW38	P1.0,D2.0,D1.1	EMTA	Ambit	AMBI381	U10C021	4.71.1001	2.31		
CW38	D2.0,D1.1	CM	Arris	ARRI381	TM502G	4.5.0	01		
CW38	P1.0,D2.0,D1.1	EMTA	Cisco-Linksys, LLC	LINK381	CMP300B	17.0.5.23	58.0		
CW38	P1.0,D2.0,D1.1	EMTA	Cisco-Linksys, LLC	LINK382	CMP200B	2.0.3.7.16	1.0		
CW38	C1.1,D2.0,D1.1	Embedded PS	Cisco-Linksys, LLC	LINK383	WCG104	2.0.3.7.16	2.0		
CW38	C1.1,D2.0,D1.1	Embedded PS	Motorola	MOTO381	SBG940	SBG940-2.1.1.1-SCM01-NOSH	1		
CW38	P1.0,D2.0,D1.1	EMTA	Motorola	MOTO382	SBV5200	SBV5200-2.1.3710.1-SCM00-SH	1		
CW38	P1.0,D2.0,D1.1	EMTA	Motorola	MOTO383	SBV5121	SBV5121-2.17.5.23-SCM01-NOSH	1		
CW38	DSG,D2.0,D1.1	DSG+ECM	Pace Micro Technology	PACE381	TDC775D	3.7.16001	V1.0		Verified for Interoperability
CW38	P1.0,D2.0,D1.1	EMTA	Pace Micro Technology	PACE382	DV315	v05.38.01	V1.0		
CW38	P1.0,D2.0,D1.1	EMTA	Scientific Atlanta	SCIE381	DPC2223	v2.0.2r1154	1.0		
CW38	P1.0,D2.0,D1.1	EMTA	Scientific Atlanta	SCIE382	DPC2203	v2.0.2r1254	1.0		
CW38	P1.0,D2.0,D1.1	EMTA	Thomson	THOM381	DHG535	ST70.01.00	1.0		
CW38	P1.0,D2.0,D1.1	EMTA	Thomson	THOM382	DHG525	ST62.08.00	5.0		
CW38	D1.1	CM	Tollgrade	TOLL381	1.0.0	1.0.2	1.0.0		
CW37	D2.0,D1.1	CM	Asustek	ASUS371	ACM6049EB	3.7.7	3.00		
CW37	D2.0,D1.1	CM	Motorola	MOTO371	SB5121	SB5121-2.17.0.12-SCM01-NOSH	1.0		
CW37	P1.1,P1.0	CMS	Nortel Networks	0NORT371	CS 2000 CMS	SN08.PSC	SN08.PHC		
CW37	P1.1,P1.0	MGC	Nortel Networks	3NORT371	CS 2000 MGC	SN08.PSM	SN08.PHM		
CW37	P1.1,P1.0	MG	Nuera Communications	4NUER371	BTX-4K	1.1	A		
CW37	P1.1,P1.0	CMS	Siemens	0SIEM371	Surpass hiQ 8000	08.04.01.US.05	Sun Microsystems Netra 1400T		
CW37	P1.1,P1.0	MGC	Siemens	3SIEM371	Surpass hiQ 8000	08.04.01.US.05	Sun Microsystems Netra 1400T		

CERT_WAVE_NAME	SPECS_CERTIFIED	PRODUCT_TYPE_NAME	MANUFACTURER	CABLELABS_NAME	MODEL_NUM	SOFTWARE_REVISION	HARDWARE_REVISION	OEM_VENDOR_ID	CB_DECISION_PUBLIC_COMMENT
CW37	D2.0.D1.1	CM	Turbocomm	TURB371	EC420	17.0.1.11	29.2		
CW35	D2.0.D1.1	CM	Arris	ARRI351	TTM402P Phase 2	4.4.1	32		
CW35	D2.0.D1.1	CM	Toshiba	TOSH351	PCX3200	8.43.2	25.0.0		
CW35	D1.1	CM	Toshiba	TOSH352	PCX2000	2.1R.007	3.2.1		
CW34	P1.0.D2.0.D1.1	EMTA	Ambit	AMBI341	U10C017	4.36.1018	2.22		
CW34	D2.0.D1.1	CMTS	Bigband Networks	2BIGB341	Cuda 12000 (C12-DM2x8-2.0	R6.0.0	Rev 4		
CW34	PCMM	Policy Server	CableMatrix	5CABL341	ODSP	0.8.6	NA		
CW34	PCMM	Policy Server	Camiant	5CAMI341	CAMS-2275	2.0.0	Intel SR 1300 Server		
CW34	PCMM	Policy Server	C-Cor	5CCOR341	Not Applicable	1.0	Not Applicable		
CW34	P1.1.P1.0	MG	Cisco	4CISC341	MGX8880	5.50	VXSM		
CW34	P1.0.D2.0.D1.1	EMTA	Cisco-Linksys, LLC	LINK341	CM2P2B	2.0.3.5.10	2.1		
CW34	P1.0.D2.0.D1.1	EMTA	Cisco-Linksys, LLC	LINK342	CG2P2WB	2.0.3.5.10	2.1		
CW34	PCMM.D2.0.D1.1	CMTS+MM	Motorola	2MOTO341	BSR 64000	4.1.0T08P10.12.KRAU	CHS-0009-01		
CW34	P1.0.D2.0.D1.1	EMTA	Netgear	NTGR341	CVG824G	3.5.8R01	1.00		
CW34	P1.0	MG	Nuera Communications	4NUER341	BTX-4K	1.1.0.4	A		
CW34	P1.0	CMS	Sonus	0SONU341	ASX Access Server	V06.01.00F004	SUNFIRE V120		
CW34	PCMM	Policy Server	Tazz Networks	5TAZZ341	TAZZ PCS	PCMM 1.2	SUN V60/V20z		
CW34	PCMM	Policy Server	Telcordia	5TELC341	Policy Manager 1.0	PS-R1.0-200502091200	SUNW.Ultra-80		
CW34	P1.0.D2.0.D1.1	EMTA	Terayon	TERA341	TJ945	16.0.0.9	31.0		
CW34	P1.0.D2.0.D1.1	EMTA	Thomson	THOM341	DHG525	ST62.06.00	5.0		
CW33	C1.1.D2.0.D1.1	Embedded PS	Ambit	AMBI331	U10C019	5.66.1000	4.10		
CW33	D2.0.D1.1	CM	Cisco-Linksys, LLC	LINK331	BEFCMU10 ver. 5	2.0.3.5.6	2.0		
CW33	P1.0.D2.0.D1.1	EMTA	Cisco-Linksys, LLC	LINK332	CM2P2B	2.0.3.5.6	2.1		
CW33	P1.0.D2.0.D1.1	EMTA	Cisco-Linksys, LLC	LINK333	CG2P2WB	2.0.3.5.6	2.1		
CW33	P1.0.D2.0.D1.1	EMTA	Scientific Atlanta	SCIE331	DPX2203	v2.0.2r1151	2.1		
CW33	P1.0.D2.0.D1.1	EMTA	Scientific Atlanta	SCIE332	DPX2213	v2.0.2r1251	1.0		
CW33	P1.0.D2.0.D1.1	EMTA	Thomson	THOM331	DHG525	ST62.05.00	5.0		
CW32	D2.0.D1.1	CMTS+DSG	Arris	2ARRI321	C4-CMTS-2100-1	CMTS_V04.02.00.10	2.0		
CW32	D2.0.D1.1	CM	Arris	ARRI321	TM402G	4.4.1	07		
CW32	D1.1	CMTS+DSG	Bigband Networks	1BIGB321	Cuda 12000 (C12-DM2x8-2.0	R5.5.0	Rev 4		
CW32	C1.1.D2.0.D1.1	Embedded PS	Cisco-Linksys, LLC	LINK321	CG2P2WB	2.0.3.4.2	2.0		
CW32	D2.0.D1.1	CMTS+DSG	Motorola	2MOTO321	BSR 64000	4.1.0T08P10.KRAU	CHS-0009-01		
CW32	C1.1.D2.0.D1.1	Embedded PS	Netgear	NTGR321	CG814WG	3.4.2	1.02		
CW32	DSG.D1.0	DSG+ECM	Scientific Atlanta	SCIE321	8300 DVLPR	2.23.7	1.0		Verified for Interoperability
CW32	D2.0.D1.1	CM	Terayon	TERA321	TJ716x	15.0.0.20	56.1		
CW32	C1.1.D2.0.D1.1	Embedded PS	Thomson	THOM321	DCW725	ST5A.06.01	4.1		
CW32	D1.1	CM	Tollgrade	TOLL321	1.0.0	1.0.2	1.0.0		
CW32	D2.0.D1.1	CM	Zoom	ZOOM321	5241	5.35.33.5	100	CONE291	
CW32	C1.1.D2.0.D1.1	Embedded PS	Zyxel	ZYXE321	Prestige 971	V3.70.01	V4.1		
CW32	C1.1.D2.0.D1.1	Embedded PS	Zyxel	ZYXE322	Prestige 974	V3.70.01	V3.9		
CW31	D1.1	CM	AM Communications	AMCO311	9362	1.68	4.0		
CW31	P1.1.P1.0.D1.1	CMTS+PC	Cisco	1CISC311	uBR7246 VXR/MC28U	12.2(15)BC2p1	MC28U Rev 6.5		
CW31	D1.1	CM	Electroline	ELEC311	DHT-PS-NA-01	2.14	02		
CW31	P1.0.D2.0.D1.1	EMTA	Motorola	MOTO311	SBV5220	SBV5220-2.10.0.0-SCM11-NOSH	1		
CW31	D1.1	CM	Tollgrade	TOLL311	1.0.0	1.0.2	1.0.0		* This product is certified only for the uses as defined in the executive summary of the certification application.
CW30	P1.0.D2.0.D1.1	EMTA	Ambit	AMBI301	U10C017	4.36.1007	2.22		
CW30	P1.0.D2.0.D1.1	EMTA	Cisco-Linksys, LLC	LINK301	CM2P2B	2.0.3.2.5	2.0		
CW30	P1.0.D2.0.D1.1	EMTA	Cisco-Linksys, LLC	LINK302	CG2P2WB	2.0.3.2.5	2.0		
CW30	D1.1	CM	Electroline	ELEC302	DHT-PS-NA-01	2.10	01		
CW30	D2.0.D1.1	CMTS	Motorola	2MOTO301	BSR 64000	4.1.0T04P15.KRAU	CHS-0009-01		
CW30	D2.0.D1.1	CM	Motorola	MOTO301	SBV5220	SBV5220-2.9.1.0-SCM08-NOSH	1		
CW30	P1.0.D2.0.D1.1	EMTA	Scientific Atlanta	SCIE301	DPX2203	v2.0.2r1143	2.1		
CW30	D2.0.D1.1	CM	Terayon	TERA301	TJ716x	14.0.1.4101	35.0		
CW30	C1.1.D2.0.D1.1	Embedded PS	Thomson	THOM302	DCW725	ST5A.02.01	4.0		
CW29	D1.1	CMTS	ADC	1ADCO291	Cuda 12000 (C12-DM2x8-2.0	R5.5.0	Rev 4		
CW29	D2.0.D1.1	CM	Ambit	AMBI291	U10C018	2.93.1003	1.20		

CERT_WAVE_NAME	SPECS_CERTIFIED	PRODUCT_TYPE_NAME	MANUFACTURER	CABLELABS_NAME	MODEL_NUM	SOFTWARE_REVISION	HARDWARE_REVISION	OEM_VENDOR_ID	CB_DECISION_PUBLIC_COMMENT
CW29	D2.0.D1.1	CMTS	Arris	2ARRI291	C4-CMTS-2100-1	CMTS_V04.00.00.104	2.0		
CW29	P1.0	MG	AudioCodes	4AUDC291	Mediant 5000	2.0.30_1.6	Rev. B		
CW29	D2.0.D1.1	CM	Cisco-Linksys, LLC	LINK291	BEFCMU10 ver. 4	2.0.3.1.1	2.0		
CW29	C1.1.D2.0.D1.1	Embedded PS	Cisco-Linksys, LLC	LINK292	WCG200 ver. 2	2.0.3.1.1	2.0		
CW29	C1.1.D2.0.D1.1	Embedded PS	Cisco-Linksys, LLC	LINK293	CGV2W	2.0.3.1.1	2.0		
CW29	D2.0.D1.1	CM	Conexant	CONE291	ACM951	5.35.33.5	100		
CW29	D2.0.D1.1	CM	Conexant	CONE292	XCM951	5.35.33.5	10		
CW29	P1.0	MG	General Bandwidth	4GENE291	G6	rel_1001_0_0_BP	1.0		
CW29	P1.1.P1.0.D1.1	CMTS+PC	Motorola	1MOTO291	BSR 64000	3.1.0T00P57.05.KRBU	CHS-0009-01		
CW29	D1.1	CMTS	Motorola	1MOTO292	BSR 64000	3.1.0T00P57.05.KRBU	CHS-0009-01		
CW29	D2.0.D1.1	CM	Motorola	MOTO291	SB5120	SB5120-2.13.0.2-SCM05-NOSH	4		
CW29	P1.0.D2.0.D1.1	EMTA	Motorola	MOTO292	SBV5120	SBV5120-2.9.0.1-SCM16-NOSH	1		
CW29	D2.0.D1.1	CM	Scientific Atlanta	SCIE291	WebSTAR DPC2100	v2.0.2r1142	1.2		
CW29	D2.0.D1.1	CM	Scientific Atlanta	SCIE292	WebSTART DPC2100	v2.0.2r1242	2.0		
CW29	D2.0.D1.1	CM	Thomson	THOM291	DCM425	ST52.01.02	4.0		
CW28	D2.0.D1.1	CM	Ambit	AMBI281	10018EU	2.93.1000	1.18		
CW28	C1.0.D1.1	Embedded PS	Ambit	AMBI282	60740EU	5.11.1111	4.7		
CW28	D2.0.D1.1	CMTS	Arris	2ARRI281	710622	4.0.1.45	04		
CW28	P1.0.D2.0.D1.1	EMTA	Arris	ARRI281	TM402P	TS.04.01.01.013004C	04		
CW28	D2.0.D1.1	CM	Askey Computer Corp.	ASKE281	CME100	2.0.2.0.6	2.1		
CW28	D2.0.D1.1	CM	Castlenet	CAST281	DP1110XB2A	2.7.2.280	1.0		
CW28	D2.0.D1.1	CM	Castlenet	CAST282	DP1110XB2	2.5.2.117	1		
CW28	P1.1.P1.0.D1.1	CMTS+PC	Cisco	1CISC281	uBR7246 VXR/MC28U	12.2(15)BC2p	MC28U: Rev 6.5		
CW28	C1.1.D2.0.D1.1	Embedded PS	Cisco-Linksys, LLC	LINK281	WCG200	2.0.2.10.0	1.2b		
CW28	D2.0.D1.1	CM	Conexant	CONE281	ACM951	5.29.30.6.MOOB	100		
CW28	D2.0.D1.1	CM	Conexant	CONE282	XCM951	5.29.30.6.MIAMI	010		
CW28	D2.0.D1.1	CM	Daehanet, Inc.	DAEH281	LP3200	10.2.0	29.2	JHCO261	
CW28	D2.0	CM	Dlink	DLIN281	DCM-202	2.0.1	1A	HITR252	
CW28	D1.1	CM	Electroline	ELEC281	DHT-PS-NA-01	2.00	01		
CW28	D2.0.D1.1	CM	Motorola	MOTO281	SBG940	SBG940-2.1.8.1-SCM00-NOSH	1		
CW28	C1.0.D2.0.D1.1	Embedded PS	Motorola	MOTO282	SBG940	SBG940-2.1.8.1-SCM00-NOSH	1		
CW28	D2.0.D1.1	CM	Motorola	MOTO283	SBV5120	SBV5120-2.8.0.4-SCM02-NOSH	1		
CW28	D2.0.D1.1	CM	Motorola	MOTO286	SBG900	2.1.8.2SCM01	3		
CW28	D2.0.D1.1	CM	Motorola	MOTO287	SB5101	SB5101-2.4.0.1-SCM00-NOSH	1		
CW28	C1.1.D2.0.D1.1	Embedded PS	Netgear	NTGR281	CG814WG	2.10.0R01	1.02		
CW28	P1.0	MGC	Nortel Networks	3NORT281r1	CS 2000 MGC	SN06.PSM	SN06.PHM		
CW28	D2.0.D1.1	CM	Shenzhen Coship Electronics Co., Ltd	COSH281	CCM2000A	12.0.2.13	35.0		
CW28	P1.0	CMS	Siemens	OSIEM281	Surpass hiQ 8000	06.02.01.US.09	Sun Microsystems Netra 1400T		
CW28	D2.0.D1.1	CM	Thomson	THOM281	DCM325	ST32.0D.00	1.7		
CW28	D1.0	CM	Thomson	THOM282	DCM325	ST31.08.01	1.7		
CW28	D1.1	CM	Toshiba	TOSH281	PCX1100/DAZ8	1.8.022	6.11		
CW28	D1.1	CM	Toshiba	TOSH282	PCX1100U/DAZ8813	1.8.022	6.62		
CW27	C1.0	Embedded PS	Ambit	AMBI272	60740EUW	5.11.1111	4.7		
CW27	D1.1	CM	BestData	BEST271	CMX300v2	0.14457.2570	10	CAST261	
CW27	D2.0	CM	Cablerex	CABL271	CRM3800	7.0.2	6.0.1	XROS241	
CW27	P1.0	CMS	Cedar Point	OCEDA271	SAFARI	R3.0.9.3	1.2		
CW27	P1.0	CMS	Cisco	0CISC271	BTS10200	RLS 4.1Q11	BTS10200		
CW27	D1.1	CMTS	Cisco	1CISC271	uBR7246VXR/MC28U	12.2(15)CXc1	MC28U: Rev. 6.2		
CW27	P1.0	MGC	Cisco	3CISC271	BTS10200	RLS 4.1Q11	BTS10200		
CW27	D2.0	CM	Cisco-Linksys, LLC	LINK271	BEFCMU10 ver. 3	2.0.2.0.1	1.0		
CW27	C1.0	Embedded PS	Motorola	MOTO271	SBG900	SBG900-2.1.6.2-SCM02-NOSH	2		
CW27	D2.0	CM	Motorola	MOTO272	SBG900	SBG900-2.1.6.0-SCM04-NOSH	2		
CW27	D2.0	CM	Motorola	MOTO273	SB5100	SB5100-2.3.1.6-SCM01-NOSH	3		
CW27	C1.0	Embedded PS	Netgear	NTGR271	CG814WG	2.92R01	1.02		
CW27	P1.0	EMTA	Scientific Atlanta	SCIE271	WebSTAR DPX2203	v2.0.1r1133	1.1		

CERT_WAVE_NAME	SPECS_CERTIFIED	PRODUCT_TYPE_NAME	MANUFACTURER	CABLELABS_NAME	MODEL_NUM	SOFTWARE_REVISION	HARDWARE_REVISION	OEM_VENDOR_ID	CB_DECISION_PUBLIC_COMMENT
CW27	C1.0	Embedded PS	Scientific Atlanta	SCIE272	WebSTAR DPR2320	v2.0.1r1133	1.1		
CW27	D2.0	CM	Scientific Atlanta	SCIE273	WebSTAR DPC2100	v2.0.1r1133	1.1		
CW27	D2.0	CM	Scientific Atlanta	SCIE274	WebSTAR DPX2100	v2.0.1r1134	1.3		
CW27	P1.0	CMS	Telcordia	TELC271	Telcordia Call Agnet	2.3.3	Sun Ultra 80		
CW27	D2.0	CM	Terayon	TERA272	TJ815g	4.21.5	41.0		
CW27	D2.0	CM	Thomson	THOM271	DCM315	ST32.0A.00	3.1		
CW27	D2.0	CM	Toshiba	TOSH271	PCX2600/DAZ8823	3.0.14	19.0.1		
CW27	D2.0	CM	Zyxel	ZYXE271	Prestige 964 CM/Router WG	3.61	3.6		
CW26	P1.0	CMTS+PC	ADC	1ADCO261	Cuda 12000	R5.0.0	CMTS: Rev 4		
CW26	D1.1	CM	Ambit	AMBI261	60678EU	2.57.1002	1.12		
CW26	D1.1	CMTS	Arris	1ARRI261	CMTS 2000	3.2.1.100.001	02		
CW26	D2.0	CM	Askey Computer Corp.	ASKE261	CME100	2.0.2.0.1	2.1		
CW26	D1.1	CM	Belkin	BELK261	F5D5530-W	0.14457.2571	10		
CW26	D1.1	CM	Castlenet	CAST261	CXC150	0.14457.2570	10		
CW26	D1.1	CM	Castlenet	CAST262	CXC250	5.19.20.2.FORTMESH.2561	010		
CW26	P1.0	CMS	Cedar Point	0CEDA261	SAFARI	2.0.7.3	1.1		
CW26	D1.1	CM	Cisco	CISC261	Ubr925	12.2	3.1		
CW26	D2.0	CM	JooHong	JHCO261	SL2810	10.2.0	29.2		
CW26	D2.0	CM	Motorola	MOTO261	SB5100	SB5100-2.3.0.9-SCM01-NOSH	3		
CW26	D2.0	CM	Motorola	MOTO262	SBG900	SBG900-2.1.3.4-SCM09-NOSH	1		
CW26	D1.1	CM	Motorola	MOTO263	SBG1000	SBG1000-1.1.3.5-SCM00-NOSH	1		
CW26	D1.1	CM	Motorola	MOTO264	SB3100	SB3100-1.4.8.13-SCM01-NOSH	1		
CW26	C1.0	Embedded PS	Netgear	NTGR261	CG814WG	2.90R01	1.02		
CW26	P1.0	CMS	Nortel Networks	0NORT261	CS 2000	SN06.PSC	SN06.PHC		
CW26	P1.0	MG	Nuera Communications	4NUER261	BTX-8	2.0	2.0		
CW26	D1.0	CM	Scientific Atlanta	SCIE261	WebSTAR DPX2100	v.1.0.1r1131-0424	1.11		
CW26	C1.0	Embedded PS	Scientific Atlanta	SCIE263	WebSTAR DPR2320	v2.0.1r1132	1.1		
CW26	P1.0	EMTA	Scientific Atlanta	SCIE264	WebSTAR DPX2203	v2.0.1r1132	1.1		
CW26	D2.0	CM	Scientific Atlanta	SCIE265	WebSTAR DPC2100	v2.0.1r1132	1.0		
CW26	D1.1	CM	SMC	SMCN262	SMC8004CM	2.0.1	1A	HITR251	
CW26	D2.0	EMTA	Terayon	TERA262	TA-102	6.0.1v	9.3		
CW26	D2.0	CM	Terayon	TERA263	TJ715X	6.22	10.0		
CW26	D2.0	CM	Texas Instruments	TEXA261	TNETC421A	10.2.4	51.2		
CW26	D1.1	CM	The Linksys Group, Inc.	LINK261	BEFCMU10 ver 3	1.1.1.0.1	1.0		
CW26	D1.1	CM	The Linksys Group, Inc.	LINK263	WCG200	1.1.3.0.1	1.2b		
CW26	D1.1	CM	The Linksys Group, Inc.	LINK264	WCG200	1.1.3.0.1	1.2b		
CW26	D1.0	CM	Thomson	THOM261	DCM315/DCM315R	ST31.07.00	1.3		
CW26	D1.0	CM	Thomson	THOM262	DCW625/DCW625R	ST41.03.00	1.1		
CW26	D2.0	CM	Thomson	THOM263	DCM316/DCM316R	ST36.10	50.1		
CW26	D1.0	CM	Thomson	THOM264	DCM315, DCM315R (retail)	ST31.08.00	1.5		
CW26	D1.1	CM	Thomson	THOM265	DCW615 (DCW615R)	ST49.04.00	1.4		
CW26	P1.0	EMTA	Toshiba	TOSH262	PCX3000	7.2.3	13.0.0		
CW26	D1.1	CM	Toshiba	TOSH263	PCX2200/DAZ8817	1.8.017	7.4		
CW26	D2.0	CM	Zyxel	ZYXE261	Prestige 964	3.60	3.6		
CW25	D2.0	CM	Ambit	AMBI251	60678EU	2.57.2007	1.12		
CW25	C1.0	Embedded PS	Ambit	AMBI253	60740EUW	5.11.1001	4.6		
CW25	P1.0	CMTS+PC	Arris	1ARRI251	C4-CMTS-2100-1	CMTS_V03.01.00.20	1.3		
CW25	P1.0	EMTA	Arris	ARRI251	TTM202P	TM.03.02.020703C	05		
CW25	D1.1	CM	Arris	ARRI252	CM450A	CM.04.02.011703C	01		
CW25	D2.0	CM	Arris	ARRI253	CM450A	CM.04.02.011703C	01		
CW25	D2.0	CM	Castlenet	CAST253	CXC250	5.12.12.1	010		
CW25	P1.0	CMS	Cisco	0CISC251	BTS10200	R4.0	R4.0		
CW25	P1.0	CMTS+PC	Cisco	1CISC251	uBR10012	12.2(11)BC2p	Rev 4.0 MC28 Rev A0		
CW25	D1.1	CMTS	Cisco	1CISC252	uBR7114	12.2(11)BC3c	Rev 1.3		
CW25	P1.0	CMTS+PC	Cisco	1CISC253	uBR7246vvr	12.2(11)BC2p	rev B0, MC16S rev 1.0, NPE400: RevA0, HW 1.03		
CW25	D2.0	CM	Com21	CMT0251	DP1110XB2	2.5.2.111	1		

CERT_WAVE_NAME	SPECS_CERTIFIED	PRODUCT_TYPE_NAME	MANUFACTURER	CABLELABS_NAME	MODEL_NUM	SOFTWARE_REVISION	HARDWARE_REVISION	OEM_VENDOR_ID	CB_DECISION_PUBLIC_COMMENT
CW25	D1.1	CM	Correlant	CORR251	EC330A	9.2.9	17.0		
CW25	D1.1	CM	Dlink	DLIN251	DCM-201	1.1.0	4A	HITR231	
CW25	D1.0	CM	DX Antennae	DXAN251	CDM-130/DAZ8821	1.0.6	9.1.1	TOSH221	
CW25	D1.1	CM	Hitron	HITR251	BRG-35201	2.0.1	1A		
CW25	D2.0	CM	Hitron	HITR252	BRG-3520T	2.0.1	1A		
CW25	D1.1	CM	Kinpo	KIPO251	CMD1001	5.26	7.0		
CW25	P1.0	CM	Motorola	1MOTO251	BSR 64000	1.3.0T04P21.KRAU	PCA-0100		
CW25	D1.1	CM	Motorola	MOTO252	SB5120	SB5120-2.9.2.9-SCM-03-NOSH	1		
CW25	D2.0	CM	Motorola	MOTO253	SB5120	SB5120-2.9.2.9-SCM-03-NOSH	1		
CW25	P1.0	EMTA	Motorola	MOTO255	SBV4200	SBV4200-07.2.04-SCM00-NOSH	1		
CW25	D2.0	CM	Motorola	MOTO256	SB5120	SB5120-2.9.3.9-SCM-03-NOSH	2		
CW25	D1.1	CM	Motorola	MOTO259	SB3100	SB3100-1.4.8.13-SCM00-NOSH	1		
CW25	D1.1	CM	Netgear	NTGR251	CG814Mv2	2.0.0	1A		
CW25	D2.0	CM	Scientific Atlanta	SCIE251	WebSTAR DPX2100	2.0.1r1.1.3.1	1.1		
CW25	D1.1	CM	Scientific Atlanta	SCIE252	WebSTAR DPX100	1.1.2r1.1.3.1	2.1		
CW25	D1.1	CM	SMC	SMCN253	SMC8013WG	2.0.0	1A		
CW25	P1.0	CMS	Sydeo	OSYND251	SYION426	2.2.6.8	SUNBLADE1000		
CW25	P1.0	CM	Terayon	2TERA251	BW-3500	2.0.0.1.21	2.0		
CW25	D1.1	CM	Terayon	TERA251	TA-102	2215	8.15		
CW25	D1.1	CM	Terayon	TERA252	TJ715	5.26	9.0		
CW25	D2.0	CM	Terayon	TERA253	TJ715	6.20	9.0		
CW25	D2.0	CM	Terayon	TERA254	TJ715	6.20	7.0		
CW25	D1.1	CM	Terayon	TERA255	TJ715X	5.25	7.0		
CW25	D1.1	CM	The Linksys Group, Inc.	LINK251	BEFCMU10	1.1.5	3.0		
CW25	D2.0	CM	The Linksys Group, Inc.	LINK255	WCG200	2.0.1.0.1	1.0b		
CW25	C1.0	Embedded PS	The Linksys Group, Inc.	LINK256	WCG200	2.0.1.0.2	1.0b		
CW25	D1.1	CM	The Linksys Group, Inc.	LINK257	WCG200	2.0.1.0.1	1.0b		
CW25	D1.0	CM	Thomson	THOM251	DCM315, DCM315R	ST31.04.00	1.2		
CW25	D2.0	CM	Thomson	THOM252	DCM315, DCM315R	ST32.06.00	1.2		
CW25	D1.1	CM	Thomson	THOM253	DCW615, DCW615R	2.81R01	1.40		
CW25	C1.0	Embedded PS	Thomson	THOM254	DCW615, DCW615R	2.82R03	1.40		
CW25	D1.0	CM	Toshiba	TOSH251	PCX2600/DAZ8823	1.0.13	19.0.0		
CW25	D2.0	CM	Toshiba	TOSH252	PCX2600/DAZ8823	3.0.13	19.0.0		
CW25	D1.0	CM	Toshiba	TOSH253	PCX4500/DAZ8841	1.0.0	17.0.0		
CW24	D1.1	CM	Ambit	AMBI241	60194E	2.23.1099	1.6		
CW24	D1.1	CM	Ambit	AMBI242	60678EU	2.57.1001	1.12		
CW24	D1.1	CMTS	Arris	ARRI242	ARCD00048	4.2.8	01		
CW24	P1.0	EMTA	Arris	ARRI241	TM02DB102	3.5.1	04		
CW24	D1.1	CM	Arris	ARRI241	TM02DB102	3.5.1	04		
CW24	D1.1	CM	Arris	ARRI242	TC00DA103	4.2.0	01		
CW24	D1.1	CM	Arris	ARRI243	TC00DA1430	1.1.0	02		
CW24	D1.1	CM	Askey Computer Corp.	ASKE241	CME100	1.1.1 r1	1.0		
CW24	D1.1	CM	Broadxent	BROA241	8601	1.1.5 r1	5.2		
CW24	P1.0	CM	Cisco	1CISC241	UBR7246 VXR	12.2(11)BC1c	Rev B0 MC16S rev 1.0, NPE400		
CW24	D1.1	CMTS	Cisco	1CISC241	UBR10012	12.2(11)BC2c1	Rev 3.0 MC5x20S rev. 5.0		
CW24	D1.1	CM	Cisco	1CISC242	uBR7200 VXR	12.2(11)BC1c	rev B0, MC16S rev 1.0, NPE400: Rev A0, HW 1.03		
CW24	D1.1	CM	Com21	CMT0241	DP1110XB2	2.5.2.110	1		
CW24	D1.1	CM	Kinpo	KIPO241	CMD1001	5.25	7.0		
CW24	D1.1	CM	Motorola	MOTO242	SB5100	SB5100-1.1.1.1-SCM01-NOSH	1		
CW24	D2.0	CM	Motorola	MOTO243	SB5100	SB5100-1.1.1.1-SCM01-NOSH	1		
CW24	C1.0	Embedded PS	Netgear	NTGR241	CG314WH	2.64	1.30		
CW24	D1.1	CM	Pioneer	PION241	BT-M850W	1.1.1.r1	1.0		
CW24	D1.1	CMTS	Scientific Atlanta	SCIE231	Prisma G1	2.1.1.16B	M2.0-G1	1Unpr231	
CW24	D2.0	CM	Scientific Atlanta	SCIE241	WebSTAR DPX2100	2.0.1 r4	1.1		
CW24	P1.0,D1.1	EMTA	Scientific Atlanta	SCIE242	WebSTAR DPX203	1.0.4 r4	5.0		

CERT_WAVE_NAME	SPECS_CERTIFIED	PRODUCT_TYPE_NAME	MANUFACTURER	CABLELABS_NAME	MODEL_NUM	SOFTWARE_REVISION	HARDWARE_REVISION	OEM_VENDOR_ID	CB_DECISION_PUBLIC_COMMENT
CW24	D1.1	CM	Scientific Atlanta	SCIE243	WebSTAR DPR362	1.1.1r3	1.0		
CW24	P1.0	CMTS+PC	Terayon	2TERA241	BW3500	2.0.0.0.21	2.0		
CW24	D2.0	CMTS	Terayon	2TERA241	BW3500	2.0.0.0.21	2.0		
CW24	D1.1	EMTA	Terayon	TERA241	TA-102	221	8.15		
CW24	D1.1	CM	Terayon	TERA242	TJ715	5.25	7.0		
CW24	D2.0	CM	Terayon	TERA243	TJ715	6.19	3.0		
CW24	D1.1	CM	Texas Instruments	TEXA241	CX3000	8.2.2	200.2		
CW24	D2.0	CM	Texas Instruments	TEXA242	TNETC406	27.8.2	13.1		
CW24	C1.0	Embedded PS	The Linksys Group, Inc.	LINK241	BEFCMUH4	2.64	1.30		
CW24	D1.0	CM	Thomson	THOM241	DCM315	ST31.01.00	1.1		
CW24	D1.0	CM	Thomson	THOM242	DCM305 and DCM305R (retail)	ST23.1B.41	028		
CW24	D1.1	CM	Thomson	THOM244	DCM318/318R	5.25	8.0		
CW24	P1.0,D1.1	EMTA	Toshiba	TOSH241	PCX3000/DAZ8831	6.2.3	13.0.0		
CW24	D1.0	CM	Toshiba	TOSH243	PCX2200A/DAZ8818	1.7.022	7.6		
CW24	D1.1	CM	Toshiba	TOSH245	PCX201/DAZ7781	1.0.0	17.0.0		
CW24	D2.0	CM	Xrosstech	XROS241	XCM-3800	7.0.2	6.0.1		
CW23	D1.1	CM	Arris	ARRI231	CM00DA103	3.3.0	01		
CW23	D1.1	CM	Askey Computer Corp.	ASKE231	CME075	1.1.4 r1	5.4		
CW23	D1.1	CM	Belkin	BELK231	F5D5530-W	0.13645-2310	10		
CW23	D1.1	CM	Castlenet	CAST231	CXC150	0.13645.2310	10		
CW23	D1.1	CM	Com21	CMT0231	DP1110XB	2.3.2.109	3		
CW23	D1.0	CM	Efficient Networks	EFFI231	SpeedStream 6101	2.22.2	1.8		
CW23	D1.1	CM	Fujitsu	FNTS231	FSC102	1.1.2 r1	5.1	ASKE211	
CW23	D1.1	CM	Hitron	HITR231	BRG-3520	1.1.0	4A		
CW23	D1.1	CM	Intel	INTE231	5200	14.5.4	9		
CW23	D1.1	CMTS	Juniper Networks	1JNPR231	Juniper G1	2.1.1.16b	M2.0-G1		
CW23	D1.1	CMTS	Motorola	1MOTO231	BSR 64000	1.3.0T03P08A.KRBU	PCA-0100		
CW23	D1.0	CM	Motorola	MOTO231	SBG1000	SBG1000-0.1.1.1-SCM03-NOSH	1		
CW23	D1.0	CM	Motorola	MOTO232	SB4300	2.7.1b	1		
CW23	D1.0	CM	Netgear	NTGR231	CM212	1.01	3A	HITR201	
CW23	D1.0	CM	Netgear	NTGR232	CG814W	2.63	1.10		
CW23	D1.0	CM	Scientific Atlanta	SCIE231	WEBSTAR DPX100	1.0.5 r1.1.3	2.1		
CW23	D1.0	CM	Scientific Atlanta	SCIE232	Webstar DPX 2100	2.0.1r	1.0		
CW23	D1.0	CM	SMC	SMCN231	SMC8012WG	2.63	1.00		
CW23	D1.1	CMTS	Terayon	1TERA231	BW3500	1.3.21.2	2.0		
CW23	D1.1	CM	The Linksys Group, Inc.	LINK231	BEFCMUH4	2.63	1.30		
CW23	D1.1	CM	The Linksys Group, Inc.	LINK233	BEFCMU10 Ver 2	1.1.4	4.0		
CW23	D1.1	CM	Thomson	THOM231	DCM305/DCM305R	ST24.13.40	028		
CW23	D1.0	CM	Thomson	THOM232	DCW232	2.63	1.30		
CW23	D1.0	CM	Toshiba	TOSH231	PCX2500/DAZ8821	1.0.11	9.2.3		
CW23	D1.0	CM	Toshiba	TOSH232	PCX5000/DAZ8850	1.7.021SV	7.31		
CW23	D1.0	CM	Toshiba	TOSH233	PCX2200/DAZ8817	1.7.021	7.4		
CW22	D1.1	CM	3Com	3COM221	3CR29223	02.06	2.00		
CW22	D1.1	CMTS	ADC	1ADCO221	Cuda 12000 (C12-DM1x6SPM-SF)	R3.1.23	CMTS: Rev A5		
CW22	D1.1	CMTS	ADC	1ADCO222	Cuda 12000 (C-12-DM1x4SPM-SF)	R3.1.23	CMTS Rev. 23		
CW22	D1.1	CMTS	Arris	1ARRI221	C4-CMTS-2100-1	v02.00.02.10	1.0		
CW22	D1.1	CMTS	Arris	1ARRI222	ARCD00048	4.2.6	01		
CW22	D1.0	CM	Asustek	ASUS222	ACM6045EB	1.9	1.4		
CW22	D1.1	CM	Broadxent	BROA221	8601	1.1.2 r1	5.1	ASKE211	
CW22	D1.1	CMTS	Cisco	1CISC221	UBR7200VXR/MC28C	12.2(7)BC1c	NPE-400: Rev A0 HW 1.03, MC28C: Rev B0 HW 2.03		
CW22	D1.0	CM	Com21	CMT0221	DP 1110XB	2.3.1.108	3		
CW22	D1.1	CM	Com21	CMT0222	DP 1110XB	2.3.2.108	03		
CW22	D1.1	CM	Correlant	CORR221	EC270	1.8.10	7.41		
CW22	D1.1	CM	Fujitsu	FNTS221	FSC102	1.1.2 r1	5.1	ASKE211	
CW22	D1.1	CM	JooHong	JHCO222	SL-2800	Ver6.1.0	Ver2.1		
CW22	D1.1	CMTS	Juniper Networks	1JNPR221	Juniper G10	2.1.0.18	2.0		
CW22	D1.1	CMTS	Motorola	1MOTO221	BSR 64000	1.2.47.KRC	PCA-0057-02		
CW22	D1.1	CMTS	Motorola	1MOTO222	BSR 1000	01.01.15.PRR	PCA-0027-030		

CERT_WAVE_NAME	SPECS_CERTIFIED	PRODUCT_TYPE_NAME	MANUFACTURER	CABLELABS_NAME	MODEL_NUM	SOFTWARE_REVISION	HARDWARE_REVISION	OEM_VENDOR_ID	CB_DECISION_PUBLIC_COMMENT
CW22	D1.0	CM	Motorola	MOTO221	SB4220	SB4220-0.6.3.0-SCM-01-NOSH	1		
CW22	D1.1	CM	Motorola	MOTO222	SB4220	SB4220-1.6.3.0-SCM-01-NOSH	1		
CW22	D1.1	CM	Motorola	MOTO223	SB4100	1.4.8.5	0		
CW22	D1.1	CM	Motorola	MOTO224	SB4200	SB4200-1.4.8.4-SCM01-NOSH	1		
CW22	D1.0	CM	Pioneer	PION221	BT-M800W	1.0.7 r1	3.0		
CW22	D1.1	CMTS	Scientific Atlanta	1SCIE221	Prisma G10	2.1.0.18	2.0	1JNPR221	
CW22	D1.0	CM	Scientific Atlanta	SCIE221	WebStar DPX100	1.0.5 r1.1	1.0		
CW22	D1.0	CM	Scientific Atlanta	SCIE222	WebStar DPX100	1.0.5 r1.1	2.1		
CW22	D1.0	CM	Scientific Atlanta	SCIE223	WebStar DPX100	1.0.5 r1.1	2.2		
CW22	D1.1	CM	Texas Instruments	TEXA221	TNETC405T	6.3.0	9.1		
CW22	D1.0	CM	The Linksys Group, Inc.	LINK222	BEFCMUH41	1.0.0	0A		
CW22	D1.0	CM	The Linksys Group, Inc.	LINK223	BEFCMUH4	2.62	1.10		
CW22	D1.0	CM	Thomson	THOM221	DCM305/305R	ST22.05.01	028		
CW22	D1.0	CM	Thomson	THOM222	DCM305/305R	ST23.10.00	028		
CW22	D1.0	CM	Toshiba	TOSH221	PCX2500/DAZ8821	1.0.6	9.1.1		
CW22	D1.1	CM	Toshiba	TOSH222	PCX2500/DAZ8821	2.0.7	9.2.2		
CW22	D1.0	CM	Toshiba	TOSH224	PCX2200	1.7.017	7.3		
CW21	D1.0	CM	Aastra	AAST211	HM300c	71-0001-10	ROA 219 767/1 R1A		
CW21	D1.1	CMTS	ADC	1ADCO211	Cuda 12000	R3.1.91	20		
CW21	D1.1	CMTS	Arris	1ARRI212	C4-CMTS2100	V01.01.00.12	1.0		
CW21	D1.1	CM	Arris	ARRI211	A2TM02NA	2.1.0	04		
CW21	D1.1	CM	Askey Computer Corp.	ASKE211	CME075	1.1.2 r1	5.1		
CW21	D1.0	CM	Asustek	ASUS211	ACM6045EB	1.80	1.00		
CW21	D1.0	CM	BestData	BEST211	CMX300	0.5096.360	04	CAS1191	
CW21	D1.1	CMTS	Cisco	1CISC211	UBR10012	12.2(4)8Cc	Rev 4.0 MC28 RevA0		
CW21	D1.1	CM	Conexant	CONE211	CX9421CM	4.12734	24943.15.0		
CW21	D1.0	CM	Coresma	CRSM211	CM6011	0.5096.360	04	CAS1191	
CW21	D1.0	CM	DX Antennae	DXAN211	CDM-120/DAZ8820	1.1R.005	3.2.1	TOSH182	
CW21	D1.0	CM	Motorola	MOTO213	SB4100	0.4.4.0p	Rev. 0		
CW21	D1.0	CM	Motorola	MOTO214	SB4200	0.4.4.0p	Rev. 1		
CW21	D1.1	CM	Quanta Network	QUAN211	QCM200	2.4.1	3.2		
CW21	D1.1	CMTS	RiverStone	1RSTN211	RS 8600	8.2.1.1	Backplane Rev A		
CW21	D1.1	CM	Samsung Electronics	SAME211	SCM-140U	2.1.0	14.00		
CW21	D1.1	CM	Scientific Atlanta	SCIE211	WebSTAR DPX100	1.1.2 r1	2.1		
CW21	D1.1	CM	Scientific Atlanta	SCIE212	WebSTAR DPX213	1.1.2 r1	1		
CW21	D1.1	CM	SMC	ACTN211	CM3503B-CSMC8011CM-B	2.3.1	3.0		
CW21	D1.1	CM	Tellabs	TELL211	CVM315A	2.5.0	RevA		
CW21	D1.0	CMTS	Terayon	0TERA212	B2800	6.1.2 C.1	300-005-03-0B	RiverStone	
CW21	D1.1	CM	Terayon	TERA211	ECM615	4.34	1.3		
CW21	D1.1	CM	Terayon	TERA212	ECM715	5.08	3.0		
CW21	D1.0	CM	The Linksys Group, Inc.	LINK211	BEFCMU10 ver.2	1.0.6	4.0		
CW21	D1.0	CM	The Linksys Group, Inc.	LINK212	BEFCMU10	1.0.4 Rel 2	3.0		
CW21	D1.1	CM	Thomson	THOM211	DCM245/DCM245R	ST.1C.0D.00	026		
CW21	D1.0	CM	Thomson	THOM212	RCA DCM305	ST22.04.00	028		
CW21	D1.1	CM	Xrosstech	XROS211	XCM-2300	V5.0.2	V5.1.2		
CW20	D1.0	CM	3Com	3COM201	3CR29223	01.22	2.00		
CW20	D1.1	CM	Ambit	AMBI201	60194E	2.25.988	1.8		
CW20	D1.0	CM	Ambit	AMBI202	60237EUW	5.1.309	4.2		
CW20	D1.1	CM	Arris	ARRI201	A2TM01NA	1.1.0	02		
CW20	D1.0	CMTS	Cisco	0CISC201	UBR10012	12.2(2)XF1	rev 3.0 MC26 rev A0		
CW20	D1.1	CMTS	Cisco	1CISC201	UBR7200 VXR/MC16S	12.1(7)CX2	rev B0 MC16S rev 1.0		
CW20	D1.0	CM	Cisco	CISC201	UBR925	Ver 12.2	31		
CW20	D1.0	CM	Dlink	DLIN201	DCM-200	4.4382.1	3.2		
CW20	D1.1	CM	Ericsson	ERIC201	HM206C	CXC 112 22391/1 R1B	ROA 117 8439/1 R2A		
CW20	D1.0	CM	Hitron	HITR201	BRG-3520	1.0.1	3A		
CW20	D1.0	CM	Motorola	MOTO201	SB4100	0.4.3.3p	Rev. 0		
CW20	D1.0	CM	Motorola	MOTO202	SB4200	0.4.3.3p	Rev.1		
CW20	D1.0	CMTS	Pacific Broadband	0PBCO201	Kodiak G10	2.0.0.16	2.0.0 (M2.0/A1.2/D2.0)		
CW20	D1.0	CM	Panasonic	PANA201	TZ-CM200	1.7.14	2.1		
CW20	D1.0	CMTS	Scientific Atlanta	0SCIA201	Prisma G10	2.0.0	2.0.0	1JNPR211	

CERT_WAVE_NAME	SPECS_CERTIFIED	PRODUCT_TYPE_NAME	MANUFACTURER	CABLELABS_NAME	MODEL_NUM	SOFTWARE_REVISION	HARDWARE_REVISION	OEM_VENDOR_ID	CB_DECISION_PUBLIC_COMMENT
CW20	D1.0	CM	Scientific Atlanta	SCIE201	WebSTAR DPX100	1.0.5 r1	1.0		
CW20	D1.1	CM	Scientific Atlanta	SCIE202	WebSTAR DPX100	1.1.1 r1	2.0		
CW20	D1.1	CM	Tellabs	TELL201	CVM410A	V3.20	V1.A		
CW20	D1.1	CM	Texas Instruments	TEXA201	TNETC405T	4.0.9	9.0		
CW20	D1.0	CM	Thomson	THOM201	RCA DCM245	ST13.05.00	26		
CW20	D1.0	CM	Toshiba	TOSH201	PCX2500 / DAZ8821	1.0.2	9.1.0		
CW20	D1.1	CM	Toshiba	TOSH202	PCX2500 / DAZ8821	2.0.2	9.1.0		
CW20	D1.1	CM	Toshiba	TOSH203	PCX3000 / DAZ8831	2.2.2	13.0.0		
CW20	D1.0	CM	Toshiba	TOSH204	PCX2200 / DAZ8817	1.7.014	7.1		
CW19	D1.0	CM	Accton	ACTN191	SMC8002CM	4.5096	9414.18.0		
CW19	D1.0	CM	Ambit	AMBI191	60194E	2.22.2	1.8		
CW19	D1.1	CMTS	Arris	ARRI191	Cornerstone CMTS 1500	4.2.0	01		
CW19	D1.0	CM	Askey Computer Corp.	ASKE191	CMH033	1.0.4 Release 2	3.0	SCIE192	
CW19	D1.0	CM	Askey Computer Corp.	ASKE192	CME063	1.0.4 Release 2	4.0	SCIE191	
CW19	D1.0	CM	Asustek	ASUS191	ACM6050EB	1.60	1.30		
CW19	D1.1	CMTS	Cadant	1CADA191	C4-CMTS-2100	v00.80.17	1.0		
CW19	D1.0	CM	Castlenet	CAST191	CXC110	0.5096.360	04		
CW19	D1.0	CM	Correlant	CORR191	EC280T	1.7.11	7.11		
CW19	D1.0	CM	Ericsson	ERIC191	HM200c	CXC 112 2096/1 R5B	ROA 117 8439/1 R2A		
CW19	D1.0	CM	Ericsson	ERIC192	HM204c	CXC 112 2096/1 R5B	ROA 117 8439/1 R2A		
CW19	D1.0	CM	Ericsson	ERIC193	HM200c	R3G	R2B		
CW19	D1.0	CM	Hauppauge Computer	HAUP191	BRG-3510	1.0.9M1.2	A0	HITR181	
CW19	D1.0	CM	HighSpeed Surfing	HIGH191	SM200	0.5096.360	02		
CW19	D1.0	CM	LG Innotek	LGIN191	LCM100	4.5096	03		
CW19	D1.0	CM	LG Innotek	LGIN192	LCM5000	1.0.9M1.2	A0	HITR181	
CW19	D1.0	CM	Motorola	MOTO191	SB4000	4.2.12p	Rev. 1		
CW19	D1.0	CM	Motorola	MOTO192	SB4100	4.0.12p	Rev. 0		
CW19	D1.0	CM	Motorola	MOTO193	SB4101	4.0.12p	Rev. 4		
CW19	D1.0	CM	Panasonic	PANA191	TZ-CM200	1.7.11	2.1	Correlant EC280T	
CW19	D1.0	CM	Samsung Electronics	SAME191	SCM-120U	1.1.1	12.20		
CW19	D1.0	CM	Scientific Atlanta	SCIE191	WebSTAR DPX110	1.0.4 Release 2	4.0		
CW19	D1.0	CM	Scientific Atlanta	SCIE192	WebSTAR DPX110	1.0.4 Release 2	3.0		
CW19	D1.0	CM	SMC	SMCN191	SMC 8002 CM	2.8.3	1.6	AMBI181	
CW19	D1.0	CM	Terayon	TERA191	ECM610	3.47	1.2		
CW19	D1.0	CM	Terayon	TERA192	ECM615	3.52	1.2		
CW19	D1.1	CM	Texas Instruments	TEXA191	TNETC405	2.0.1	2.0.0		
CW19	D1.0	CM	The Linksys Group, Inc.	LINK191	BEFCMU10	1.0.3 Release 4	3.0	NORT171	
CW19	D1.0	CM	Thomson	THOM191	DCM245 / DCM245R	ST12.07.01	26		
CW19	D1.0	CM	Toshiba	TOSH192	PCX1500/DAZ8816	1.7.011	7.1		
CW19	D1.1	CM	Toshiba	TOSH193	PCX2500/DAZ8821	2.0.1	9.00		
CW19	D1.0	CM	Toshiba	TOSH194	PCX1200/DAZ8815	1.7.011	7.0		
CW19	D1.0	CM	Tri-Gem Computer	TRIG191	Dream Port-1200	1.0.9M1.2	A0	HITR181	
CW19	D1.0	CM	Turbocomm	TURB191	EC200T	1.7.11	7.0		
CW19	D1.0	CM	Zoom	ZOOM191	Zoom Cable Modem 5041	4.100	140		
CW18	D1.0	CM	3Com	3COM181	3CR29250	2.10.5	1.6	Ambit	
CW18	D1.0	CM	3Com	3COM183	3CR29250	2.16.1	1.6	Ambit	
CW18	D1.0	CM	Ambit	AMBI181	60194E	2.8.3	1.6		
CW18	D1.0	CM	Castlenet	CAST181	CXC-110-DualLink	0.4590.230	04		
CW18	D1.0	CM	Dlink	DLIN181	DCM-200	4.4382	3.2	POWE171	
CW18	D1.0	CM	Ericsson	ERIC181	HM200c	CXC112 2096/1 R5A	ROA117 8439/1 R2A		
CW18	D1.0	CM	Ericsson	ERIC182	HM204C	CXC112 2096/1 R5A	ROA117 8439/1 R2A		
CW18	D1.0	CM	Ericsson	ERIC183	HM200c	R3D	R2B		
CW18	D1.0	CM	HighSpeed Surfing	HIGH181	SM100	0.4381.108	04	CAST172	
CW18	D1.0	CM	Hitron	HITR181	BRG-3510	1.0.9M1.2	A0		
CW18	D1.0	CM	Hitron	HITR182	BRG-3511	1.0.9W1.3	A0		
CW18	D1.0	CM	Infinite	INF181	ICM1150T	VCMxM v1.8	ICM1150T Rev D		
CW18	D1.0	CM	Net & Sys	NETS181	MNG2000	2.1.0	4.0		
CW18	D1.0	CMTS	Pacific Broadband	OPBCO181	Kodiak F10	1.1.0.17	M1.1 / A1.7 / D1.1		
CW18	D1.0	CM	Samsung Electronics	SAME181	SCM-120U	1.0.0	12.20		
CW18	D1.0	CM	The Linksys Group, Inc.	LINK181	BEUCM11	0.4381.108	04	CAST172	
CW18	D1.0	CM	Thomson	THOM181	DCM245/245R	ST12.07	26		
CW18	D1.0	CM	Toshiba	TOSH181	PCX 2000/DAZ8820	1.1R.006	3.3.2		

CERT_WAVE_NAME	SPECS_CERTIFIED	PRODUCT_TYPE_NAME	MANUFACTURER	CABLELABS_NAME	MODEL_NUM	SOFTWARE_REVISION	HARDWARE_REVISION	OEM_VENDOR_ID	CB_DECISION_PUBLIC_COMMENT
CW18	D1.0	CM	Toshiba	TOSH182	PCX 2000/DAZ8820	1.1R.005	3.2.1		
CW18	D1.0	CM	US Robotics	USRO181	USR6000	2.13.2	1.6	Ambit	
CW18	D1.0	CM	Zoom	ZOOM181	5001	1.86	0295-014 (MIB:295014)		
CW17	D1.0	CM	3Com	3COM172	3CR29223	01.15	2.0		
CW17	D1.0	CM	3Com	3COM173	3CR29241	01.03	2.0		
CW17	D1.0	CM	Accton	ACCT171	SMC 8001	2.1.0	2/1		
CW17	D1.0	CMTS	Arris	0ARRI171	Cornerstone CMTS-1500	4.0	00		
CW17	D1.0	CM	Askey Computer Corp.	ASKE171	CME063	1.0.3R4	3.0		
CW17	D1.0	CM	Castlenet	CAST171	CXC110-iCabler	0.4381.108	04		
CW17	D1.0	CM	Castlenet	CAST172	CXC110-CTI	0.4381.108	04		
CW17	D1.0	CMTS	Cisco	0CISC172	UBR 7100	ubr7100-k1p-mz.121-4.4.EC	Line card rev 3 upconv.rev7		
CW17	D1.0	CM	Cisco	CISC171	CVA 122	cva120-k1v4y5.mz.TLN	3.t		
CW17	D1.0	CM	Dakos	DAKO171	CableXpert CM21100	4.0.43.81	1.0		
CW17	D1.0	CM	Elsa	ELSA171	Microlink Cable	1.0.8	A3	GVC	
CW17	D1.0	CM	Ericsson	ERIC171	HM200c R1A (ZAT 510 102/14)	R3D	R1A		
CW17	D1.0	CM	Ericsson	ERIC172	HM204c R1A (ZAT 510 112/14)	R4A	R1A		
CW17	D1.0	CM	Global Teleman	GTSC171	MediaLynx CM-2000	K	MediaLynx CM-2000 Rev. 0.5		
CW17	D1.0	CM	HighSpeed Surfing	HIGH171	SM110	0.4381.108	04	CAST172	
CW17	D1.0	CM	Matsushita	MATS171	TZ-CM100	1.1	1.1		
CW17	D1.0	CM	Motorola	MOTO171	SB3100	3.2.12p	Rev. 1		
CW17	D1.0	CM	Motorola	MOTO172	SB4100 Rev 0	4.2.1p	Rev. 1		
CW17	D1.0	CM	Motorola	MOTO173	SB4100 Rev 0	4.0.9p	Rev. 0		
CW17	D1.0	CM	Motorola	MOTO174	SB4100 Rev 1	4.0.9p	Rev. 1		
CW17	D1.0	CM	Nortel Networks	NORT171	CM115U	1.0.3R4	3.0	ASKE171	
CW17	D1.0	CM	Powercom	POWE171	PCR-2600U	4.4382	V3.2		
CW17	D1.0	CMTS	RiverStone	0RSTN171	RS 8000	6.1.2.C.1	Backplane: 300-001-05-0A CMTS module: 02		
CW17	D1.0	CM	Samsung America	SAMA171	SCM-130U	V2.1.0	13/10		
CW17	D1.0	CM	Samsung Electronics	SAMS171	SCM-120R	4.4381	12.00		
CW17	D1.0	CM	Scientific Atlanta	SCIE171	Webstar DPX-110	1.0.3R4	3.0	ASKE171	
CW17	D1.0	CMTS	Tellabs	0TELL171	Cablesplan 2700	6.1.2.C.1	Backplane: 300-005-06-0A CMTS module: 02		
CW17	D1.0	CMTS	Terayon	0TERA171	BE 2000/BE-CMTS41	6.1.2.C.1	Backplane: 300-001-05-0A CMTS module: 02		
CW17	D1.0	CM	Terayon	TERA171	ECM210	1.7.8	6.62	Correlant	
CW17	D1.0	CM	Texas Instruments	TEXA171	TNETC400G	.217	3.2		
CW17	D1.0	CM	The Linksys Group, Inc.	LINK171	BEUCM11	0.4381-108	04	CAST172	
CW16	D1.0	CM	Ambit	AMBI161	60218.P	v2.2 patch-9	v3.1		
CW16	D1.0	CMTS	Cisco	0CISC161	uBR7200/MC28C	12.1(3a)EC	A0		
CW16	D1.1	CMTS	Cisco	1CISC161	uBR7200/MC16S	12.1(5)pokemon	A0		
CW16	D1.0	CM	Dlink	DLIN161	DCM100	4.4270	3.2		
CW16	D1.0	CM	Elsa	ELSA161	204	1.30	G		
CW16	D1.0	CM	Nortel Networks	NORT161	CM220	2.4.1	1.4	Ambit	
CW16	D1.0	CMTS	RiverDelta	0RDEL161	BSR64000	00.01.00.BA	CHS-0001-02		
CW16	D1.0	CM	Toshiba	TOSH161	DAZ8813	1.7.007	6.62		
CW16	D1.0	CM	Zoom	ZOOM161	5031	2.0.42.70	029301		
CW15	D1.0	CM	3Com	3COM151	3CR29223(USB)	1.10	2.00		
CW15	D1.0	CM	Ambit	AMBI151	60194E	2.2.7	1.4		
CW15	D1.0	CM	Arris	ARRI151	CM200R	ST1.08	25	Thomson	
CW15	D1.0	CM	Askey Computer Corp.	ASKE151	RT080	1.10.0	8.0		
CW15	D1.0	CM	CIS	CISS151	WS-CM30ED1E	v2.14	1.0		
CW15	D1.0	CMTS	Cisco	0CISC151	UBR 7200 VXR	12.1(2)EC1	A0		
CW15	D1.0	CM	Cisco	CISC151	UBR905	Ubr925-kik2o3sv4y5-mz	A0		
CW15	D1.0	CM	Com21	CMTO151	DP1110	2.1.0.100	6		
CW15	D1.0	CM	DeltaKabel	LUCE151	Deemos 38-033	V2.91.0	v8.0	Aske131	
CW15	D1.0	CM	Elsa	ELSA151	204	1.18	E		
CW15	D1.0	CM	Future Networks	FUTU152	FN110C	V2.15	V1.C		
CW15	D1.0	CM	Maspro	MASP151	77TCM2	V1.0	V1.C		
CW15	D1.0	CMTS	Motorola	0MOTO151	DCM 2000 475390-001-00	1.0	475995-001-00 Rev 01		
CW15	D1.0	CM	Motorola	MOTO152	SB3100 Rev C	Rev v3.2.9	Rev C		

CERT_WAVE_NAME	SPECS_CERTIFIED	PRODUCT_TYPE_NAME	MANUFACTURER	CABLELABS_NAME	MODEL_NUM	SOFTWARE_REVISION	HARDWARE_REVISION	OEM_VENDOR_ID	CB_DECISION_PUBLIC_COMMENT
CW15	D1.0	CM	Net & Sys	NETS151	MNG-1000	2.20d	1.03		
CW15	D1.0	CM	OL'E Communications	OLEE151	HC1001	1.0.3657	01		
CW15	D1.0	CMTS	RiverDelta	ORDEL151	BSR1000	2.1.9	BSR 1000		
CW15	D1.0	CMTS	RiverStone	ORSTN151	RS8000	6.1.0.1	Chassis Rev B CMTS Model Rev 02		
CW15	D1.0	CM	Saejin	SAEJ151	SC-5100E	1.13	1.2		
CW15	D1.0	CMTS	Terayon	OTERA151	Teralink 2000 TLL-CMTS41A	6.1	Chassis: revB, CMTS: Rev. 2		
CW15	D1.0	CM	Terayon	TERA151	TJ110/ECM110	1.7.6	6.12		
CW15	D1.0	CM	Terayon	TERA152	TJ210/ECM210(USB)	1.7.6	6.62		
CW15	D1.0	CM	Terayon	TERA153	TCM310	0036-58	D		
CW15	D1.0	CM	Thomson	THOM151	DCM235/235R(USB)	ST1.08	25		
CW15	D1.0	CM	Toshiba	TOSH152	PCX1100 DAZ8811	1.7.006	6.12		
CW15	D1.0	CM	Toshiba	TOSH153	PCX1100U DAZ8813(USB)	1.7.006	6.62		
CW14	D1.0	CM	Ambit	AMBI141	60098U	2.0.5	2.0		
CW14	D1.0	CM	Ambit	AMBI142	60098E	2.0.13	1.3		
CW14	D1.0	CMTS	Arris	0ARRI142	CMTS-1000	3.2.1	Rev 08		
CW14	D1.0	CM	Arris	ARRI141	CM200U	RCA Broadband	ST 5.14	RCA	
CW14	D1.0	CM	Asustek	ASUS141	ACM6000EB	2.3	1.3		
CW14	D1.0	CMTS	Cisco	0CISC141	UBR 7200 VXR	12.0(11)SC	A0		
CW14	D1.0	CM	Com21	CMT0141	DP121	1.6.19	6.6	TurboNet Communications	
CW14	D1.0	CM	Dlink	DLIN141	DCM100	0.44.32.52	Rev 2.3	PowerCom	
CW14	D1.0	CM	DX Antennae	DXAN141	DAZ8811	1.7.003	6.11	TOSH131	
CW14	D1.0	CM	Ericsson	ERIC141	HM200c	Rev R1D	Rev. R2B		
CW14	D1.0	CM	Ericsson	ERIC142	HM200c	Rev R1E	Rev R2B		
CW14	D1.0	CM	GVC	GVCC141	CMI-004/CON	Rev 1.44.32.52	Rev 31		
CW14	D1.0	CMTS	Motorola	0MOTO142	MLLN 4004D	5.2	Engine, MVME2306-900 MRX. 74267G01, Rev C		
CW14	D1.0	CM	Motorola	MOTO141	SB3100 Rev D	Rev v3.2.6	Rev D		
CW14	D1.0	CM	Motorola	MOTO143	SB3100 Rev C	Rev v3.2.6	Rev C		
CW14	D1.0	CM	Powercom	POWE141	PCR2600	0.44.32.51	Rev 2.3		
CW14	D1.0	CM	Samsung Electronics	SAMS141	SCM-110R Ether	Rev 2.0.2	Rev 11.10		
CW14	D1.0	CM	Terayon	TERA141	ECM 210	Rev 1.6.19	Rev 6.6	TurboNet	
CW14	D1.0	CM	Thomson	THOM141	DCM 225	Ver 5.14	Ver 25		
CW14	D1.0	CM	Zoom	ZOOM141	0110-Z5001-02-00-00	1.44.32.52	0295-01		
CW14	D1.0	CM	Zoom	ZOOM142	011-Z5011-02-00-0001	0.44.32.52	0293-01C		
CW13	D1.0	CMTS	3Com	03COM134	80-000971-01	3.61.48-1	Rev 1.0		
CW13	D1.0	CMTS	3Com	03COM135	8R-003678-10	4.4.18	Rev B		
CW13	D1.0	CM	3Com	3COM131	3CR29210	3.1.0	B.2		
CW13	D1.0	CM	3Com	3COM132	3CR29220	1.04	2.00		
CW13	D1.0	CM	3Com	3COM133	3CR29220	1.0.4	2.00		
CW13	D1.0	CM	Alcatel	ALCA131	uM141	1.7.3	6.10		
CW13	D1.0	CM	Askey Computer Corp.	ASKE131	CME033	V2.91.0	v8.0		
CW13	D1.0	CMTS	BAS	0BASS131	Cuda	0.1.58	D		
CW13	D1.0	CM	BestData	BEST131	CMX110	1.7.3	6.10		
CW13	D1.0	CM	Cisco	CISC131	UBR924	ubr920-k1y5-mz.1208TLN	A0		
CW13	D1.0	CM	Future Networks	FUTU131	100L	v2.13	v2.2		
CW13	D1.0	CM	Future Networks	FUTU132	110L	v2.13	v1.0		
CW13	D1.0	CM	GVC	GVCC131	CMX-SO	3.10	B		
CW13	D1.0	CM	JooHong	JOOH131	Superink 2000	1.7.3	6.1		
CW13	D1.0	CM	Motorola	MOTO133	SB3100 Rev C	v3.2.1	Rev C		
CW13	D1.0	CM	Netgame	NETA131	Phazer	2.80	6.0	ASKE121	
CW13	D1.0	CM	Netgear	NETG131	CM201	2.80	6.0	ASKE121	
CW13	D1.0	CM	Nortel Networks	NORT131	CM115	V2.91.0	V8.0		
CW13	D1.0	CM	SOHOware	SOHO131	NSC200	1.7.3	6.10		
CW13	D1.0	CM	Toshiba	TOSH131	DAZ8811	1.7.003	6.11		
CW13	D1.0	CM	Toshiba	TOSH132	DAZ8813	1.6.018	6.6		
CW13	D1.0	CM	Zyxel	ZYXE131	941	V2.4	Zygate GM V1.58		
CW12	D1.0	CM	3Com	3COM121	2940	2.03	L3		
CW12	D1.0	CM	Arris	ARRI121	CM200	ST 4.06	V24		
CW12	D1.0	CM	Arris	ARRI122	CM200	ST 5.05	V25		
CW12	D1.0	CM	Askey Computer Corp.	ASKE121	CME030	v2.80	v6.0		

CERT_WAVE_NAME	SPECS_CERTIFIED	PRODUCT_TYPE_NAME	MANUFACTURER	CABLELABS_NAME	MODEL_NUM	SOFTWARE_REVISION	HARDWARE_REVISION	OEM_VENDOR_ID	CB_DECISION_PUBLIC_COMMENT
CW12	D1.0	CM	Com21	CMT0123	DP111	1.6.16	6.1		
CW12	D1.0	CM	Dassault	DASS121	WD020	v2.80	v6.0		
CW12	D1.0	CM	HighSpeed Surfing	HIGH121	SM100	1.6.16	6.1	TURB121	
CW12	D1.0	CM	Motorola	MOTO121	MLN6200A	1.0CL08	75087G01		
CW12	D1.0	CM	Motorola	MOTO122	MMLN3150A	2.0.051	74362G01		
CW12	D1.0	CM	Terayon	TERA121	ECM100	1.6.16	6.1		
CW12	D1.0	CM	Terayon	TERA122	ECM110	1.6.16	5.4		
CW12	D1.0	CM	Thomson	THOM121	DCM215	ST5.05	V24		
CW12	D1.0	CM	Thomson	THOM122	DCM215	ST4.0b	V24		
CW12	D1.0	CM	Thomson	THOM123	DCM225	ST5.05	V25		
CW12	D1.0	CM	Toshiba	TOSH121	DAZ8811	1.7.002	6.1		
CW12	D1.0	CM	Toshiba	TOSH122	DAZ881	1.6.016	6.1		
CW12	D1.0	CM	Turbocomm	TURB121	CM110	1.6.16	6.1		
CW11	D1.0	CM	BestData	BEST111	CMX100	1.6.14	5.4		
CW11	D1.0	CMTS	Cisco	OCISC111	UBR7200	11.3(11a)NA1	A0		
CW11	D1.0	CM	Com21	CMT0111	CP3001	1.0.1.100	6500087 revSA		
CW11	D1.0	CM	Com21	CMT0112	CP3001	1.0.5.100	6500106revSS		
CW11	D1.0	CM	Com21	CMT0113	CP3001	1.1.0.100	6500106revSS		
CW11	D1.0	CM	Com21	CMT0114	DP101	1.6.14	5.40		
CW11	D1.0	CM	Com21	CMT0115	DP101	1.6.14	5.4		
CW11	D1.0	CM	DX Antennae	DXAN111	DAZ8801D	1.6.003	5.21	TOSH092	
CW11	D1.0	CM	General Instruments	GENE111	SB3100A	v3.0.7	-002RevA		
CW11	D1.0	CM	General Instruments	GENE112	SB3100B	v3.0.7	-001RevB		
CW11	D1.0	CM	Thomson	THOM111	DCM 205	ST 1.10	ver 16		
CW10	D1.0	CM	Terayon	TERA101	ECM100	1.6.9	5.4		
CW10	D1.0	CM	Thomson	THOM101	DCM105	ST 20.5.3	HW Ver 12		
CW09	D1.0	CMTS	Arris	0ARRI091	DE3801E02	2.0.0	03		
CW09	D1.0	CM	Askey Computer Corp.	ASKE091	CME010	1.76	1.11		
CW09	D1.0	CM	Cisco	CISC091	UBR904	11.3(9)NA ubr900-k1-y4-mz.cablelabs.13may99	A0		
CW09	D1.0	CMTS	Motorola	0MOTO091	MMLN004D	5.0.0t10	MAC, 74029G01, Rev A Engine, MVME3206-900MTX-HI,		
CW09	D1.0	CM	Motorola	MOTO091	MMLN4004D	5.0t10p13b	MAC, 74029G01, Rev A Engine, MVME2306-900MTX-HI, 7		
CW09	D1.0	CM	Philips	PHIL091	PD10D	1.76	1.11		
CW09	D1.0	CM	Samsung Electronics	SAMS091	SCM-100R	1.1.76	1.2		
CW09	D1.0	CM	Sony	SONY091	CMR-1000	1.1 (0.76.1)	1.1		
CW09	D1.0	CM	Toshiba	TOSH092	PCX1000/DAZ8801F	Ver 1.6.003	Ver 5.21		
CW08	D1.0	CM	3Com	3COM081	3CR292-DE56	12.30	A01-3		
CW08	D1.0	CMTS	Arris	0ARRI081	DE3804E25	1.100.3	02		
CW08	D1.0	CM	General Instruments	GENE081	SB2100	V1.1.1	X3/0002		
CW07	D1.0	CMTS	Cisco	OCISC071	UBR7200	11.3(7)NA	A0		
CW07	D1.0	CM	Thomson	THOM071	DCM 105	ST8.4	Pilot 3 c Rev's		
CW07	D1.0	CM	Toshiba	TOSH071	DAZ8801E	1.51k	5.2		